B.R. No: 826/Date: 09/1/2015

Inspection report for the work of : Maintenance of Borewells at Chikkasandra & Shettyhalli, in SSD, in Ward no. 12

Chief Engineer

Dasarahalli Zone

BBMP, Bangalore

Inspection Report

Name of Work	:	**Maintenance of Borewells at Chikkasandra & Shettyhalli, in SSD, in Ward no. 12**
Work Order	:	No. EE/DD/WO/ 257 /13-14, Dated: 15/02/2014
Agency	:	S. Prakash
B.R. No & Dated	:	826/Date: 09/1/2015
Bill Amount	:	Rs. 1498375
Job Code	:	012-14-000010
P. Code	:	P1771

Date of Inspection : 10.7.2015

The Location of the Borewell is inspected by me along with concerned Engineers and ascertained that as Borewell maintenance works such as removing and refixing of the pipe (GI) line in the Borewell for repairing the motor is carried out as shown in the photo Enclosed

ಮುಖ್ಯ ಅಭಿಯಂತರರು/7/2015
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ಪಲಯ, ಬೆಂಗಳೂರು